

Certificate

Standard **ISO 9001:2015**

Certificate Registr. No. **01 100 98061**

Certificate Holder: **GESTAMP METALBAGES**
c/ Les Arenes, 1
08251 SANTPEDOR Barcelona
Spain

including the locations according to annex

Scope: Design and production of metallic chassis parts and production of metallic body parts by cold stamping, welding and painting

Proof has been furnished by means of an audit that the requirements of ISO 9001:2015 are met.

Validity: The certificate is valid from 2018-02-13 until 2021-02-12.
First certification 2018

2019-06-13


TÜV Rheinland Cert GmbH
Am Grauen Stein · 51105 Köln



Annex to certificate

Standard **ISO 9001:2015**

Certificate Registr. No. **01 100 98061**

No.	Location	Scope
/02	GESTAMP ABRERA, S.A. Poligono Industrial Ca n'Estella, s/n 08635 SANT ESTEVE SESROVIRES Spain	Production of metallic car body and chassis parts by cold stamping, hot stamping and welding and laser cutting
/03	Gestamp Navarra, SA Poligono Industrial Arazuri- Orkoién, calle C 31160 Orkoién (Navarra) Spain	Production of metallic car body and chassis parts by stamping, hydroforming, welding & shotpeening
/05	GESTAMP ARAGON, S.A. P.I El Pradillo, General Motors 6 50690 PEDROLA (ZARAGOZA) Spain	Production of metallic car body and chassis parts by cold stamping, hot stamping and welding
/09	GESTAMP METALBAGES, S.A. C/ Les Arenes, 1 PI Santa Anna II 08251 SANTPEDOR Spain	Design and production of metallic chassis parts and production of metallic body parts by cold stamping, welding and painting

Annex to certificate

Standard **ISO 9001:2015**

Certificate Registr. No. **01 100 98061**

/15 **GESTAMP MANUFACTURING
AUTOCHASIS, S.L.** Design and production of metallic chassis parts
Poligono Industrial El Pradillo, and production of metallic body parts by
Calle Aneto 5 welding, assembly and painting
50690 PEDROLA (ZARAGOZA)
Spain

2019-06-13


TÜV Rheinland Cert GmbH
Am Grauen Stein · 51105 Köln

Page 2 of 2